



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

JOHNSON ET AL.

Serial No. : 09/915,668

Patent No.: 6,865,695 B2

Issued: Mar. 8, 2005

For: Robust System Bus Recovery

ATTY. DOCKET NO. AUS920000904US1

§
§
§
§
§
§
§
§

Examiner: M. MASKULINKSI

Certificate

APR 04 2006

of Correction

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
P.O. Box 1450
Alexandria, Virginia 22313-1450

Sir:

Assignee respectfully submits the enclosed proposed Certificate of Correction (in duplicate), which corrects a clerical error made by the U.S. Patent and Trademark Office in Letters Patent No. US 6,865,695 B2, issued Mar. 8, 2005.

Respectfully submitted,

Brian F. Russell

Brian F. Russell
Registration No. 40,796
DILLON & YUDELL LLP
8911 N. Capital of Texas Hwy., Suite 2110
Austin, Texas 78759
512-343-6116

ATTORNEY FOR ASSIGNEE

CERTIFICATE OF MAILING
37 C.F.R. § 1.8(a)

I hereby certify that this correspondence is being deposited with the United States Postal Service as First-Class Mail in an envelope addressed to Commissioner for Patents, P.O. Box 1450, Alexandria, Virginia 22313-1450, on the date below.

3/28/06
Date

Cheryl Kilgus
Signature

APR - 4 2006

(Also Form PTO-1050)

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**PATENT NO : **US 6,865,695 B2**DATED : **Mar. 8, 2005**INVENTOR(S) : **Joyner et al.**

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In Col. 14, (Claim 16), please delete lines 4-6, and insert therefore the following:

...
--providing a recovery bus in the high speed system topology
that operates at a lower speed than the high speed
interconnect topology;--

In Col. 14 (Claim 17), please delete lines 13-16 and insert therefore the following:

--17. The method of claim 16, further including the step of:
transferring communication from the recovery bus to the
high speed interconnect topology in response to the
error being remedied.--

MAILING ADDRESS OF SENDER:

**Dillon & Yudell LLP
Suite 2110
8911 N. Capital of Texas Hwy.
Austin, Texas 78759**

PATENT NO. **US 6,865,695 B2**

No. of additional copies

1**APR - 4 2005**

(Also Form PTO-1050)

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**PATENT NO : **US 6,865,695 B2**DATED : **Mar. 8, 2005**INVENTOR(S) : **Joyner et al.**

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In Col. 14, (Claim 16), please delete lines 4-6, and insert therefore the following:

...
--providing a recovery bus in the high speed system topology
that operates at a lower speed than the high speed
interconnect topology;--

In Col. 14 (Claim 17), please delete lines 13-16 and insert therefore the following:

--17. The method of claim 16, further including the step of:
transferring communication from the recovery bus to the
high speed interconnect topology in response to the
error being remedied.--

MAILING ADDRESS OF SENDER:

Dillon & Yudell LLP
Suite 2110
8911 N. Capital of Texas Hwy.
Austin, Texas 78759

PATENT NO. **US 6,865,695 B2**

No. of additional copies

1

APR -4 2006